



Mat. Żelazo 50

TYP	d	H	C	F	h	Dh8
1210	73	25	10	9	16	60
1215	76	38	11	16	22	60
1610	83	25	10	9	16	70
1615	83	38	11	16	22	70
2012	96	32	12	10	22	90
2517	127	45	13	19	26	110
3020	152	51	18	24	27	130
3030	152	76	19	25	51	130
3525	184	65	25	25	40	155
3535	184	89	25	32	57	155
4040	225	102	35	32	70	195
4545	254	114	40	38	76	220
5050	276	127	40	38	89	242